



(W5) CONTROLLER TO MOTOR WIRING

MOTOR BRUSH END

011 To motor brush (A)

009 From control box M+

010 From control box M-

To motor brush(B) 012

CONTROLLER END

